

Code Review

- In June 2015, Energy and Mines Minister Bill Bennett appointed a Code Review Committee to determine how to implement the seven recommendations from the Independent Expert Engineering Panel's investigation into the Aug. 4, 2014, tailings pond breach at the Mount Polley Mine
- ➤ The Code Review Terms of Reference included two parts:
 - An expedited Tailings Technical Review
 - A Health and Safety Technical Review
- ➤ New provisions and requirements came into force February 2017.



Supervisor's Certification

2008 Code

· No provision

2017 Code

- Supervisor's certification has been added to ensure that supervisors at exploration sites and in mine areas such as mills, shops, warehouses and tailings storage facilities are aware of their responsibilities within the Code to ensure workers' safety
- This certification can be removed or suspended if in non-compliance
- A mine manager who supervises must have certification
- This provision comes into effect <u>June 1, 2018</u> in order to develop program and give time for compliance